

SERVICE TIPS

Troubleshooting | Rock Pickers

Situation: The Flexxifinger® Quicker Picker will not rotate.

Suggestion: Ensure that the "PRESSURE" hose is connected to the correct hose from the skid steer

loader. If issue persists, please contact the Flexxifinger Sales Support Team.

Situation: The Flexxifinger® Quicker Picker is rotating in jerking motions.

Suggestion: Ensure that the "PRESSURE" hose is connected to the correct hose from the skid steer

loader. If issue persists, please contact the Flexxifinger Sales Support Team.

Situation: There is abnormal vibration occurring.

Suggestion: Stop both the Flexxifinger® Quicker Picker and skid steer loader or tractor and inspect the

possible issue. If there is large rock or other obstruction that is too large to fit into the barrel of the Flexxifinger® Quicker Picker, reverse the skid steer loader to avoid. If there is rock or other obstruction that is the correct size to fit into the barrel of the Flexxifinger® Quicker Picker, reverse the skid steer loader, reposition and attempt to scoop again. If

issue persists, please contact the Flexxifinger Sales Support Team.

(Version 07.16) Page 1 of 1